

IIYAMA CORPORATION

ASIA headquarter

11F-3, No.51, Sec.2, Keelung Rd., Taipei,

Taiwan, R.O.C.

I Conchie, EK K Kondratowicz, EP

Tel:

Fax:

886-2-27336363

886-2-27325466

L Muller, EG J Bevivino, EA E Joor, EB T Kobayashi, JN

J Moreira, EF J Yoshino, RJ Copy:

S Kobayashi, EH

T Nakanishi, EH A Tebeest, EB N Machida, EH S Verhoeven, EB

H Depner, EG T Sugahara, GC U Zott, EG T Akimoto, RJ H Kawamura, JH

L Cheesman, EK J Pettinga, EB S Aizawa, JH

Date: Oct. 18, 2004

T Wakabayashi Pages: 1, including this pages

K Kobayashi, AH

P Butler, AH

O Uehara, AH

Engineering Change Notice No.: ECN-2229

Model:

HM703U A/UT A, HM704UC A/UTC A, HM705UC

Subject:

From:

Attn:

Prevent smoking issue

Description:

Smoke will occur from inside monitor because followings causes.

C425 is short and then some parts are burned

Q410 (H-out) is broken and then some parts are burned

Change:

To solve the problem, followings change should be implemented.

Main Board

Maiii Duaiu		
Ref. No.	New	Old
C425	C-C 2KV 220p SL (Murata)	C-C 2KV 220p Y5P
D405*	1N4148/1SS133/1SS120	-
C413*	C-E 16V 10u	-

^{*} Hole for these parts are not available on PCB, so following work is necessary.

Time of change:

Service only

Action to the units already shipped:


It has to be implemented to all returned units.

Parts supply:

Will be provided later.

Best regards,

Circuit diagram



Instructions

- 1. Cut the pattern between J051, L403 and R430.
- 2. Add electrolytic capacitor (C413) with tube to R430 (+) GND (-).
- 3. Add Diode (D405) with tube to J051, L403 (Anode) and R403 (Cathode)
- 4. Fix the added parts by silicon.

