



## REPLACEMENT OF WELDED TUB AND COUNTERWEIGHT

The welded tub part no. 126 85 72-30/0 is not available as spare part anymore.

As a replacement a welded tub part no. 126 85 75-00/6 is supplied.

**Simultaneously it is obligatory to replace also the rear counterweight.**

### SPARE PARTS

OLD			NEW		
					
Pos.	Description	Part no.	Pos.	Description	Part no.
150	Welded tub assembly	<b>Depleted</b>	150	Welded tub assembly	<b>126 85 75-00/6</b>
257	Rear counterweight	<b>126 05 19-00/2</b>	257	Rear counterweight	<b>126 05 19-50/7</b>

The affected models are listed in the following page:

<b>Models</b>	<b>PNC</b>	<b>Service Notes</b>
FA1032	914 21 10-03/00	599 349187
FA1032	914 21 10-03/01	599 359828
FA1032	914 21 10-04/00	599 348871
FA1032	914 21 10-04/01	599 359829
FA1005	914 21 10-05/00	599 350405
FA1005	914 21 10-05/01	599 359830
FA1023	914 21 10-06/00	599 350519
FA1023	914 21 10-06/01	599 359831
FA1032	914 21 10-07/00	599 350522
FA1032	914 21 10-07/01	599 359832
FA1021	914 21 10-08/00	599 348872
FA1021	914 21 10-08/01	599 359833
FA1074	914 21 10-09/00	599 348873
FA1074	914 21 10-09/01	599 359834
FA932	914 21 10-10/00	599 350949
FA932	914 21 10-10/01	599 359865
FA1032	914 21 10-11/01	599 359866
LFV1050	914 21 10-13/00	599 350956
LFV1050	914 21 10-13/01	599 359851
LC1050	914 21 10-14/00	599 350417
LC1050	914 21 10-14/01	599 359861
FA1023	914 21 10-16/00	599 353161
FA1023	914 21 10-16/01	599 359838
LVMT3100	914 21 10-22/00	599 359043
LVMT3100	914 21 10-22/01	599 359840
FA1022	914 21 40-02/01	599 359845
FA1023	914 21 40-03/00	599 359030
FA1023	914 21 40-03/01	599 359846
FA1032	914 21 40-04/01	599 359847
TF1002	914 21 40-05/00	599 356326
TF1002	914 21 40-05/01	599 359848