



SERVICE BULLETIN
Factory of Alcalá Spain

REPLACEMENT OF WASHING GROUP

We inform you that the rear and front shell of the screwed washing groups are not available anymore as spare parts.
The welded shell assembly is delivered as a replacement and can be mounted in place of the screwed one.

SPARE PARTS

PREVIOUS			NEW		
					
Pos.	Description	Part no.	Pos.	Description	Part no.
150	Shell, front, tub	Out of stock	150	Sealed tub assembly	126 85 72-30/0
150A	Shell, rear, tub	Out of stock			

The affected models are listed in the following page.

Affected models:

Model	PNC	Service Notes
FA1032	914 21 10-03/00	599 349187
FA1032	914 21 10-03/01	599 359828
FA1032	914 21 10-04/00	599 348871
FA1032	914 21 10-04/01	599 359829
FA1005	914 21 10-05/00	599 350405
FA1005	914 21 10-05/01	599 359830
FA1023	914 21 10-06/00	599 350519
FA1023	914 21 10-06/01	599 359831
FA1032	914 21 10-07/00	599 350522
FA1032	914 21 10-07/01	599 359832
FA1021	914 21 10-08/00	599 348872
FA1021	914 21 10-08/01	599 359833
FA1074	914 21 10-09/00	599 348873
FA1074	914 21 10-09/01	599 359834
FA932	914 21 10-10/00	599 350949
FA932	914 21 10-10/01	599 359865
FA1032	914 21 10-11/01	599 359866
LFV1050	914 21 10-13/00	599 350956
LFV1050	914 21 10-13/01	599 359851
LC1050	914 21 10-14/00	599 350417
LC1050	914 21 10-14/01	599 359861
FA1023	914 21 10-16/00	599 353161
FA1023	914 21 10-16/01	599 359838
LVMT3100	914 21 10-22/00	599 359043
LVMT3100	914 21 10-22/01	599 359840
FA1022	914 21 40-02/01	599 359845
FA1023	914 21 40-03/00	599 359030
FA1023	914 21 40-03/01	599 359846
FA1032	914 21 40-04/01	599 359847
TF1002	914 21 40-05/00	599 356326
TF1002	914 21 40-05/01	599 359848