CIRCUIT DIAGRAM

1. POWER SUPPLY SCHEMATIC DIAGRAM(DV-500ES)



CAUTION TO SERVICE TECHNICIANS:

BEFORE RETURING THE APPLIANCE TO THE CUSTOMER.
LEAKAGE CURRENT OR RESISTANCE MEASUREMENTS
SHOULD BE PERFORMED TO DETERMINE THAT EXPOSED
PARTS ARE PROPERLY INSULATED FROM SUPPLY CIRCUIT.

CAUTION:

THE PARTS IDENTIFIED BY ⚠ MARKS ARE CRITICAL
FOR SAFETY.
REPLACE ONLY WITH TYPE IDENTICAL TO THOSE IN THE
ORIGINAL CIRCUIT OR SPECIFIED IN THE 'PARTLIST'.
DO NOT DEGRADE THE SAFETY OF THE APPLIANCE
THROUGH IMPROPER SERVICING.