1. POWER SUPPLY SCHEMATIC DIAGRAM(VCR Middle East)



CAUTION TO SERVICE TECHNICIANS:

BEFORE RETURING THE APPLIANCE TO THE CUSTOMER.
LEAKAGE CURRENT OR RESISTANCE MEASUREMENTS SHOULD BE PERFORMED TO DETERMINE THAT EXPOSED PARTS ARE PROPERLY INSULATED FROM SUPPLY CIRCUIT.

CAUTION:

THE PARTS IDENTIFIED BY ⚠ MARKS ARE CRITICAL FOR SAFETY.
REPLACE ONLY WITH TYPE IDENTICAL TO THOSE IN THE ORIGINAL CIRCUIT OR SPECIFIED IN THE 'PARTLIST'.
DO NOT DEGRADE THE SAFETY OF THE APPLIANCE THROUGH IMPROPER SERVICING.