

E.g. , if data is located at address 100H in SDA2586, it must be at 200H in 24C16. The first 256 addresses from 0 to FF are the same for both ICs.

No hardware modifications are needed when replacing SDAxx with 24Cxx.