


2. Power(SMPS) Circuit Diagram

NOTE :  
1. Shaded(■) parts are critical for safety. Replace only with specified part number.  
2. Voltages are DC-measured with a digital voltmeter during TUNER mode.



LOCATION GUIDE

BC101	E6	R125	E3
BD101	B7	R126	E4
C101	B5	R152	J6
C102	A6	R154	I4
C103	C7	R155	I4
C105	E7	R156	J5
C106	E7	R157	J5
C107	C3	R161	J2
C108	C2	R163	K7
C109	D6	R166	I7
C110	F2	R167	J7
C112	E3	R168	J4
C113	B3	R169	J4
C114	H3	R170	J3
C115	G5	R171	J3
C116	G5	R172	I5
C117	H5	T101	F7
C120	G7	V101	B4
C121	H7	ZD152	J6
C123	G6		
C127	F3		
C129	C6		
C135	E4		
C152	K6		
C153	K5		
C154	K3		
C155	J6		
D102	D7		
D103	D6		
D104	E3		
D105	G4		
D106	G5		
D108	G7		
D109	G7		
D110	G6		
D151	I8		
D152	I7		
D157	J3		
FH01	A3		
FH02	A4		
IC101	D5		
IC102	F4		
IC103	G3		
J151	I5		
J152	J6		
L102	A5		
L103	H5		
L104	H7		
PW101	A3		
Q152	J6		
Q154	I4		
Q155	J5		
Q156	I2		
Q157	J4		
Q159	I7		
Q161	J7		
R101	B7		
R102	B6		
R103	E6		
R104	D7		
R105	B2		
R106	B6		
R109	E4		
R112	H3		
R116	G4		
R117	G3		
R118	G3		
R119	H3		
R120	H3		
R121	H2		
R122	H6		