

Product : VCR	Bulletin No. : 01-VCR-E0005
Model : COMBO(Refer to below)	Bulletin Date : 25-Aug-01
Buyer : ALL	

SUBJECT : Micom Version change And RF IC Reversion

Background : ▶ the Version change dut to Reversion of RF IC("B")

▶ application model :

SV-DVD1E/XEF SV-DVD1E/XEU SV-DVD1E/XEG SV-DVD1E/XET SV-DVD1E/XEC
 SV-DVD1E/COM SV-DVD1E/XEN SV-DVD1E/NSI SV-DVD1E/XEP SV-DVD1E/XEE
 SV-DVD1E/EUR SV-DVD1E/SED

note:

	before	after
Micom Version	SK 4.05n	SRK4.06a
RIC1	S5L1462A	S5L1462B

- ▶ Micom's name change to differentiate the previous Micom from the current Micom because they can not be replaced each other.(SK → SRK)
- ▶ only RF IC("B") can work correctly with new version name's MICOM(SRK * . * *) and RF IC("A") can work correctly with old version name's MICOM(SK * . * *)

Application Date : ALL LOT after 23th. Aug.

(Interchangeability Code : * I.C)

Location No.	OLD (before) Parts		NEW (changed) Parts		* I.C
	SEC Code	Description	SEC Code	Description	
MIC2	1102-001090	IC-EPROM M27C801-102F1	1102-001090	IC-EPROM M27C801-102F1	D
RIC1	AH13-00007A	SK 4.05n S5L1462A	AH13-00009A	SRK4.06a S5L1462B	D

Type	A type	B type	C type	D type	E type	F type
Interchange Type Code (* I.C)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	OLD → Early (Parts) (Prod.) NEW → Late (Parts) (Prod.)	Parts Addition (None → New)	Parts deletion (Old → Del.)

Application Reference (O) Only Defected sets () Whole sets ()

Attachment Schematic Diagram () Component Lay-out () Exploded View ()
 Mechanical Diagram () None (●) Others ()

Product Month : About Jun. 23. 2001

Serial No. (~ from) :

Published by :

Checked by :

Approved by Y. S. KANG