

No power.
BD101, TH101 are defective.

