

AFFECTED MODELS: All 25"AND UPPER MODELS WITH 11AK19PRO CHASSIS .

START DATE : 01.02.2002

REASONS OF CHANGE:

DEFECT OF THE RGB AMPLIFIER TDA 6108 ( IC 901 )  
TO CATCH A BETTER RELIABILITY ACCORDING SPARKS OF THE PICTURE TUBE THE CRT-BOARD  
WAS CHANGED . THIS NEW CRT BOARD AS ALSO AVAILABLE AS SPARE-PART .

**NOTE 1: WHEN THE NEW CRT-BOARD IS USED AS SPARE-PART , THE  
AVAILABLE CURRENT CONNECTOR CABLE BETWEEN CHASSIS AND CRT  
BOARD CAN BE USED .  
PAY ATTENTION FOR CONNECTING CABLE PL902 AND PL901 IN THE  
RIGHT POSITION ( SEE PHOTO )**


NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1					
2					
3					
4					
5					
6					
7					

IN



NO	PCB CODE	VESTEL CODE	COMPONENT NAME	POSITION NUMBER	QUANTITY
1	11TP19M	20090838	MD.ASY.TP19M-AK19P5 CRT BOARD		1
2					
3					
4					
5					

CUSTOMER SUPPORT ENGINEER	QUALITY MANAGER
S.DEMIRKAYA	ALI TUNC CAN


OLD CRT - BOARD



NEW CRT - BOARD



AQUA from CRT



Green CABLE must be fix to SCREW of HOLDER of Deflection coil