

## T echnical T ip

FILE	TAOSC-TT-20050308-01
DATE	08 February 2005


<b>PRODUCT</b>	CTV & PJTV
<b>Part No:</b>	Scan Module MDFS03 ( 23148027 )

### Another countermeasure

Symptom: Distortion or white peak noise appear on the screen

Cause : Poor ground at capacitor C565

Remedy: Solder the point refer to the attached Picture



Information by TAOSC Engineer  
Mr. Khoo Seng Hooi  
Mr. Stanley Lim Gee Ann