




# Maintenance kits

## Power supply repair kit for chassis TX807C/CS ( 110°)



35135370

Description	Qty	Position
1nF 5% 50V	1	CP027*
BZX55B16	1	DP021
BZX55C7V5	1	DP023
BZX55B30	1	DP027
1A6T 250V	1	FP001
TLP621 GR (D4-LF2 T)	1	IP050
100KΩ 5% 0.430W	2	RP005-RP006
4.7Ω 5% 3W	1	RP008
0.68Ω 5% 2.50W	1	RP020
10Ω 5% 0.625W	1	RP052*
STP6NB90FP	1	TP020
BC337-40	1	TP022
BC856B	1	TP031*
BC846B	1	TP032*

\* SOLDER SIDE

