


CB450B SCHEMATIC DIAGRAM



IMPORTANT SAFETY NOTICE
THE SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION AND ELECTRICAL SHOCK HAZARDS. WHEN MANUFACTURING IT IS ESSENTIAL THAT ONLY MANUFACTURERS SPECIFIED PARTS BE USED FOR THE CRITICAL COMPONENTS IN THE SYMBOL MARK OF THE SCHEMATIC.