



SUB 1/2 Schematic Diagram

WARNING: REPLACEMENT PARTS WITH THESE CRITICAL COMPONENTS WITH R SERVICING. SERVICE PERSONNEL SHOULD ACCEPTABLY INSULATED FROM THE SU




POWER SUPPLY BLOCK
SYMBOL NO. 10XX



TO VCR CL01

GND(SYS)	1
ALL +12V	2
CM -GND	3
DM -GND	4
ALL +5V(VIC HL)	5
ALL +5V(etc.)	6

TO CHROMANCE BLOCK




FUNAI

TVR-1400A

MAIN 2/2 Schematic Diagram

WARNING: REPLACEMENT PARTS WITH SPECIAL S
THESE CRITICAL COMPONENTS WITH RECOMMEN
SERVICING. SERVICE PERSONNEL SHOULD MAKE L
ACCEPTABLY INSULATED FROM THE SUPPLY CIRCU

TV μ -CON BLOCK
SYMBOL NO. 62XX



WARNING: REPLACEMENT PARTS WITH SPECIAL THESE CRITICAL COMPONENTS WITH RECOMMEN SERVICING. SERVICE PERSONNEL SHOULD MAKE ACCEPTABLY INSULATED FROM THE SUPPLY CIR

