

This content is related to Service Bulletin "MB-SB-00027".

-MX-DK1,MX-DK3,MX-DK5,MX-DK15,MX-DK51 Firmware Update Procedure -

Preparation:

* Unzip the data file(double clic the zipped file), and the data file for procedure.

* Write the data file for update in CD-R in ISO9660 format with "disc at once"

There are total 4 models in the attached files, choose the correct software when copy for upgrading.

Do not copy folder but only the 2 files in it.

Version	Download File	File Size (KB)
ALL version	MX-DK Upgrade-file.zip	223-->

Notes:

**Confirm the file size after downloading files. Using a corrupt or incomplete file may damage the unit.

**Use a blank (brand-new) CD-R or CD-RW disc.

**Copy the data with ISO9660 data format & "DISC at Once".