



**N 6/12 D-MAIN ASSY**  
**(7028069261010-IL)**

• **HDMI PART (2/2)**

N 2/12-5/12,7/12-11/12  
 N 1/12-5/12,7/12-10/12



The  $\Delta$  mark found on some component parts indicates the importance of the safety factor of the part. Therefore, when replacing, be sure to use parts of identical designation.